QUALITY CONTROL ABSTRACT (AS PER MORT&H-V REVISION)

Name of Work:Construction of CC Drains and Roads in 2nd main and 3rd main and Surrounding roads of RK Hegdenagar, Dasarahalli Village, Rchenahalli Village and Saripalya Village in Ward No.6.

Name of Agency :- Sri. P Hemanth (SOORYA CREATERS)

Bill No. :Second and Final Bill

Sl No	Description of Items	Test	Test Units	Test Per Qty	Up to Date Qty	Convertion m^3 > m^2	Convertion m^3 > Tonnes	No. Of Sample to Be Conduct for Test	No of Sample Conducted for Test
	PCC				336.25	Cum			
1	Cement Test								
		Setting Time Test - IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	3
		Soundness Test - IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	3
		Standarad Consistancy Test IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	3
2	Fine Aggregate								
		Specific Gravity and Water Absorption Test (IS 2386 Part. 3)1963	Days	One Source		-	-	1	3
		Sieve Analysis Test (IS 2386-Part 1)-1963	Days	One Source		-	-	1	3
3	Coarse Aggregate								
		Aggrgate impact Value Test (AIV) (IS 2386- Part 4)-1963	Days	One Source		-	-	1	3
		Sieve Analysis Test (IS 2386-Part 1)-1963 20 mm Aggregates	Days	One Source		-	-	1	3
		Sieve Analysis Test (IS 2386-Part 1)-1963 12.5 mm Aggregates	Days	One Source		-	-	1	3

Consultant

Asst. Executive Engineer
Project Division
Yelahanka Zone
BBMP, Bangalore - 92

Scanned by TapScanner

	M30 Concrete -				259.53	Cum			
1	Cement Test								
		Setting Time Test - IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	4
		Soundness Test - IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	4
		Standarad Consistancy Test IS 12269 (53 grade ordinary Portland cement)	Days	One Source		-	-	1	4
2	Fine Aggregate								
		Specific Gravity and Water Absorption Test (IS 2386 Part. 3)1963	Days	One Source		-	-	1	4
		Sieve Analysis Test (IS 2386-Part 1)-1963	Days	One Source		-	-	1	4
3	Coarse Aggregate								
		Aggrgate impact Value Test (AIV) (IS 2386- Part 4)-1963	Days	One Source		-	-	1	4
		Sieve Analysis Test (IS 2386-Part 1)-1963 20 mm Aggregates	Days	One Source		-	-	1	4
		Sieve Analysis Test (IS 2386-Part 1)-1963 12.5 mm Aggregates	Days	One Source		-	-	1	4
4	Cube Test								
		Compressive Strength Test (IS 516-1959)	Cum	1 Sample for 50m3				1	5
	For Road Work								
1	Granular Sub-Base (GSB)								
		Gradation	m^3	400.00	126.15	-	-	0	1
		Density of Compacted Layer	m^2	1000.00	126.15	630.75	-	1	1

Consultant

Scanned by TapScanner